United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SR00349DE

This certificate, issued to Paravion Technology, Inc.

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product — Type Certificate Number:

H2SW

Bell Helicopter Textron

Model.

407

Description of the Type Design Change:

Installation of a searchlight in accordance with Paravion Technology, Inc. Master Document List DL-407SX-100, Revision A, dated April 27, 1998, FAA approved June 26, 1998 or later approved revision.

Limitations and Conditions:

- 1. FAA Approved Rotorcraft Flight Manual Supplement dated June 26, 1998 or later approved revision is required.
- 2. A copy of this Certificate and FAA Approved Rotorcraft Flight Manual Supplement, dated June 26, 1998 or later FAA approved revision must be maintained as part of the permanent records for the modified rotorcraft.
- 3. This approval should not be extended to rotorcraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that rotorcraft.
- 4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

January 5, 1998

Date of issuance:

June 26, 1998

Date reissued:

Ronald F. May Manager Denver Aircraft Certification Office

Northwest Mountain Region, Denver, Colorado

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.